ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	9	Vidyaranyapura

Street ID	Street Name	Significant Landmark
W0665, W0436, W0663, W0659, W0657, W0633, W0639, W	NA, Mani Lyt 1st Crs, 1st Main Rd, Pattandur Agrah, 5th Crs, 8th Crs, 6th Crs Gramatana, Narayanaswa	canara bank layout

Segment No.	Total Length (m)
9/C-W0665/S084855	63.53

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	32.47	77.579847	13.068972	77.579957	13.069245	W0655	W0633
2	31.06	77.580139	13.068876	77.580242	13.069138	W0633	W0639

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements and Asphalting to roads at canara bank layout in Ward no 09 (Vidyaranayapura) Vidyaranayapura Sub-Division Yelahanka zone	4900000	2016

Year	Type of Work	Other Work Type
2016 - 2017	Asphalting	

Tender	Work Details	Job No. / Work Code
Tender	Improvements and Asphalting to roads at canara bank layout in Ward no 09 (Vidyaranayapura) Vidyaranayapura Sub-Division Yelahanka zone	009-16-000001

Work Order No.	Work Order Date	Period of Extention
BBMP/EE/BTP/WO/104/2016-17	09/08/2016	60 DAYS

Defect Liability Period From	Defect Liability Period To	Multiple road involved with the same Job No/ Work Code #
09/08/2016	08/08/2017	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
B B UMESHA		0.00

Phone No.	E-Mail ID

9886213563

Field Inspection Details

Number of Trees	Any Other Information	Name
0		JANARDHAN

Date of Inspection	Remarks
14/09/2016	COMPLETED

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 9 **Ward Name:** Vidyaranyapura **Street ID:** W0665, W0436, W0663, W0659,

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	14/09/2016	14/10/2016	COMPLETED
SE	VASU K M	14/09/2016	14/10/2016	COMPLETED
EE	YARAPPA REDDY	14/09/2016	14/10/2016	COMPLETED
AEE	SHIVAKUMAR	14/09/2016	14/10/2016	COMPLETED
AE	JANARDHAN	14/09/2016	14/10/2016	COMPLETED
AE	JANARDHAN	14/09/2016	14/10/2016	COMPLETED

Zone: YELAHANKA **Ward No:** 9 **Ward Name:** Vidyaranyapura **Street ID:** W0665, W0436, W0663, W0659,